






A technical drawing of a bolt and nut assembly. The bolt is shown in two parts: a full-length view on the left and a cross-section view on the right. The nut is shown in two views: a side view on the left and a cross-section view on the right. The bolt has a hexagonal head and a threaded shank. The nut has a hexagonal shape with a threaded bore. The drawing is a line drawing with no shading.









2 - 4








5 - 6










2 - 4






A	B	C
 CW	 UA	
50x50x0,6	50x40x2	300x620x24
75x50x0,6	75x40x2	













8




9




10



11






12













1







2



3




4







5












6



7












2a



2b



2c



3

